Work Order ID 126663  November-20-14 10:06:10 AM			*126663*								Page 1	
Item ID: Revision ID: Item Name:	Revision ID:			Accept	*N900040100			)*	Setup	Start Stop		IS1*
Start Date: Required Date: Reference:	11/20/14: 11/20/14	Start Qty: 2.00 Req'd Qty: 2.00	*9*		Cust Item 1 Customer:	ID:				·	^IVI	S2*
Approvals: Process Plan: QC:			Date: Date:	Tooling: SPC (Y/N):	Date:			Run	Start Stop		R1* R2*	
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accep Qty	t Rej		Reject Number	Insp. Stamp
Draw Nbr	Rev	vision Nbr			•							
D3407	Rev	νE							,			
*105				0.00				ə				DAS 41
SprayPaint Spray Painting			-511/512PHI 7-043 B125654	0.00								9-89 14-11-20
		RE-PAINT PHI	BLACK CAMOUFLAGE									<sub>a</sub> -t
*115 *115*		QC14- Inspect Spray Pa	aint	0.00				7	)			<b>DAS</b> <b>38</b> 9-89
QC		Memo		0.00				+				

NOV 2 1 2014

Memo

Quality Control

Work Order ID 126663 November-20-14 10:06:10 AM				*126663*							Page 2	
Item ID: Revision ID:	D3407-043			Accept	*N900	<b>040</b>	100	)* ፡	Setup Star Sto		S1*	
Item Name: Start Date: Required Date: Reference:	Tow Ring 11/20/14 11/20/14	Start Qty: 2.00 Req'd Qty: 2.00	•		Cust Item ID: Customer:					"IN	S2*	
Approvals:	Process Pla	nn:	Date:	Tooling: SPC (Y/N):	Date:			I	Run Star Stoj	<b>/IV</b>	NR1* NR2*	
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
*150 *150* Packaging Packaging		Identify as per dwg & Stoc  Memo  RETURN TO	k Location:	0.00	PDD 115611			rulula	1_5	<u> </u>		
160 *160*		QC21- Final Inspection - V	Vork Order Release	0.00					W	/11/21	4 A	
QC		Memo		0.00				~	<u> </u>	10,	-,	

Memo

Quality Control

14/11/24 A)

My 11/24 A)

My 11/24 A)